

PHOTO INDEX



Photo showing carpenters installing GWB for the ceiling on the 2nd floor.



Photo showing carpenter installing GWB on the 2nd floor ceiling.



Photo meeting hall ceiling framing taking shape. This is looking at the west end of the meeting hall.



Photo showing the roughed in closet at the north end of the platform in the meeting hall.



Photo showing plasterer working in the storage room at the south end of the platform in the meeting hall.



Photo showing HVAC workman making room for control wiring.



Photo showing HVAC mechanic installing control wiring in the basement.



Photo showing electrician continuing with the wiring installation.



Photo showing foundation wall with waterproofing and protection board (blue) installed, and insulation installed (pink).



Photo showing workmen prepping the soil to get ready for compacting.



Photo showing the compaction machine and the area after being compacted.



Photo showing soil being dumped for backfilling.

Copies to: **Richard Montuori, Town of Tewksbury**
Ed Johnson, Town of Tewksbury
Steve Sadwick, Town of Tewksbury
Wayne Lawson, CBI

Jenne dos Santos, CBI
Kaffee Kang, Kang Architects
Jennifer Pincus, Kang Architects
Bob Harukewicz, GVW Inc.